

RETAIN

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *St. Se. "CORHAVEN"*Rpt. *Sld*No. *31271*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

1st Longl
~~Transverse~~ No. *3042*

Depth "d" *12' 08'*Framing: Table No. *10062*Description *Bulk Angle, as approved*Longitudinal No. *10062*

Proportions $\frac{\text{Length}}{\text{Depth}} =$ *14' 15'*

Deck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.1 (Steel)

1 *dk* (Stl) Well *dk*.FK, 4BH, pt. *cm*, Lloyd's A9CP

Cell DB UE 18' f 140' 294t, FPT 64t, APT 15t
 MT 9' 107t

Q. 131', F. 23'.

Machinery *Aft*

The Certificate of Classification to be endorsed "Owing to the fact that the vessel is not fitted" and the same notation to be entered in the Register Book.



© 2020

Lloyd's Register Foundation

W374-0175