

replacement of Anchors or Gains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

*Cargo battens not*

TELEGRAMS: "BRANCH."

CODES:  
A.B.C. 5TH EDITION.  
WATKINS 1881 AND  
APPENDIX 1884,  
SCOTT'S.

TELEPHONE: \*NEWCASTLE 22375.

# FRANCE FENWICK TYNE AND WEAR CO., LIMITED.

SUNDERLAND.  
21, BRIDGE STREET,  
TELEGRAMS: "BRANCH."  
TELEPHONE: No. \*5416.

LONDON.  
WM. FRANCE, FENWICK & CO., LTD.  
23, ROOD LANE  
FENCHURCH STREET, E.C.3.

DIRECTORS:  
H. M. STOBART. F. W. TAYLOR.  
J. LESLIE. K. R. PELLY.  
H. F. CHARLTON.  
MANAGING DIRECTOR: F. DAWSON.

MERCANTILE CHAMBERS,  
**NEWCASTLE UPON TYNE, 1.**

16th. November, 1945.

GWB/IC  
Lloyd's Register of Shipping,  
71 Fenchurch Street,  
LONDON. E.C.3.

**SUPERINTENDENCE DEPARTMENT**

RETAIN

RECEIVED  
19 NOV 1945

Dear Sirs,

"JUTA"

ANSD.....

We are in receipt of your letter of the 15th. instant and as this vessel is sunk in deep water and is a total wreck, we do not see that there are any circumstances which should defer the step you propose to take of removing the ship's name from the Register.

Yours faithfully,

FOR FRANCE FENWICK TYNE & WEAR CO. LTD

*[Handwritten Signature]*



© 2020

Lloyd's Register  
Foundation

W375-0059

Keelsons	efficient?	Timbers of Frame at openings
Stringers	Have Ventilators and their Coamings been	

(if ass  
nd nov  
om ?  
L  
T  
sh  
m  
ded  
W  
y  
gen  
Items  
pper, or  
(State  
hen fitt  
ats  
sts, Yar  
ndition,  
(State  
quipmen  
chors, I  
bles (St  
leng  
Rul  
Chain Lo

Referred to Mr. Spray

*HB*  
*Mr Reed* *WBR*



© 2020

Lloyd's Register  
Foundation

If so, is the Report sent now, or when will it be sent?

*New*

In d  
ref

REP

*Mr*

*m*

*for*

SUMM  
*S*

PRESEN

Decks

Caulking

Coaming

Beams

Outside

"

Framee

Revers

Longit

Transv

Floors

Keelson

Stringe

ance