

Chief Surveyors _____

Received from Chief Surveyors _____

'S NAME Stl Sc LEEUWARDEN Report Gls No. 49047

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/82.)

of Survey 1st Entry When due _____ Revised Rules _____

✠ 100 A.1. (Steel). "With freeboard"

1 D^h (Stl) + Shelter D^h (Stl).

Cell D.B. 202' 30" E, F.P.T. 31" E, A.P.T. 15" E.

F.K. 5 B.H (Coll B.H to Shelter D^h, 4 B.H to 2nd D^h) Cmw, Ply do A.C.P.
B 62'.

It is concluded the size of the 2nd D^h beams is as approved but
the surveyor should be requested to state if this is so.
— L Gl 16/4/29

© 2020

11.4.29

Lloyd's Register
Foundation

W375-0210