


Steamer "CLAN MACNAB"


In connexion with endorsement dated 8th instant, the following cabled reply has now come to hand from the Batavia Surveyor, viz:-

CLAN MACNAB Owners proposal probably completed Tuesday recommend reducing 78 revolutions to 70 in fair and half speed in bad weather".

IT IS SUBMITTED that a further cablegram should be sent to the Batavia Surveyor as follows, viz:-

"If repairs carried out according to instructions and your entire satisfaction, suggest speed be left to discretion of master".


10. 6. 33


Cable 10/6/33
Bva.



© 2019

Lloyd's Register
Foundation

W377-0208

Special Damage or Repair Fee (if any)..... £

200

19