



SCALE 1:4.

REPAIR OF CRACKED SHAFT S.S. "CLAN MAC NAB"

THE CLAN LINE
STEAMERS Ltd

TANDJONG PRIOK;
12.6.33:

4778.

W377-0222

S.S. Clan Macnab

Pat. rept. No. 1125,

Crank shaft repair

RETAIN



© 2019

Lloyd's Register
Foundation
W377-0222