

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Steel Sc. CLAN MACNAB* Report *Yes* No. *49788*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey *Condition* When due _____

RETAIN

*Subject to order plate (p.s) repaired by EW 5.27
being specially examined at next drydocking.*

W.H.
14.6.29.



Lloyd's Register
Foundation

W377-0223

Without other condition.

subject to order plate (p.s) repair being examined next drydocking