


CAYZER, IRVINE & CO. LTD.

MANAGERS OF  
THE CLAN LINE STEAMERS LTD.  
LONDON, GLASGOW & LIVERPOOL.

TELEGRAMS:  
"CAYZER, STOCK, LONDON."  
"CAYZER, GLASGOW."  
"CAYZER, LIVERPOOL."  
CABLES, "CAYZER, LONDON."  
SCOTT'S CODE TENTH EDITION.  
MARCONI INTERNATIONAL CODE.



OUR REFCE  
YOUR "


TELEPHONE AVENUE 8966.

2, ST. MARY AXE,

LONDON, E.C.3.

4th. July, 1933.

The Secretary,  
Lloyd's Register of Shipping,  
LONDON, E.C.3.



Dear Sir,

s.s. "CLAN MACNAB".  
-----

When this steamer was in Batavia on the 7th. June, it was found on overhauling the Coupling between the Turbine and the Tunnel Shaft, that a longitudinal crack had developed, and your Surveyor, resident in that port, was called in by the Captain.

The cablegrams received by us regarding the repair were discussed with your principal Surveyors here, as we could not agree with the recommendations put forward by your Batavia Surveyor.

We are enclosing extracts of letters received, as we consider the whole position should be known to you.

We shall be glad to receive your views, as we are not satisfied with the attitude taken up by your Batavia Surveyor.

Yours faithfully,  
per pro CAYZER, IRVINE & CO. LTD.

General Manager.

W377-0231



Referred to the Chief Engineer Surveyor

-5 JUL 1933

Spl

*[Handwritten signature]*

ГОРДОН БЕС

БЕЛЫЯ КУРЬЯ СЪ

ГОРДОН БЕС



БЕЛЫЯ КУРЬЯ СЪ



© 2019

Lloyd's Register  
Foundation