

S.S. "CLAN MACNAB"  
S.S.No.3, due 12.32 - partly held

On 6th instant a letter was received from the Glasgow Secretary stating that the Owners desired that the dry docking carried out at Newport in February last might be taken as part of the S.S.No.3, also whether the Newport Surveyor considered it necessary for the shell plating to be drilled.

The Newport Surveyor states in reply that in his opinion the dry docking could be accepted as part of the S.S.No.3. He adds that the rudder was not lifted but appeared to be in good condition. It was not considered necessary to drill the shell plating at the time of the survey.

It is submitted the Glasgow Secretary might be informed that the dry docking referred to will be accepted as part of the Special Survey, also that the Newport Surveyor did not consider it necessary to drill the shell plating.

To complete the Special Survey the following remains to be done :- anchors and cables, chain locker and windlass to examine, and oil fuel bunker to test.

*[Handwritten signature]*  
12.9.33



© 2019

Lloyd's Register  
Foundation

W377-0240  
W377-0243

133

53789

tate  
ls  
rt  
lled