

**COPY.**

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

1st September, 1933.

Dear Sir,

S.

With reference to Glasgow Report No.53789 on the steamer "CLAN MACNAB", I shall be glad if you will be good enough to point out to the Surveyors that in addition to the items stated as remaining to complete the survey it would appear that the vessel requires to be examined in dry dock and ascertain and let me know whether it is to be concluded that it was not considered necessary to drill the shell plating.

I am, Dear Sir,

Yours faithfully,

Clerk to the  
Classification Committee.

The Secretary,  
GLASGOW.



© 2019

Lloyd's Register  
Foundation

W377-0244

W377-0245