

29th August, 1933.

W377-0246

to Chief Surveyors 30.8.33

Received from Chief Surveyors

SEL'S NAME Stl Se. "CLAN MACNAB" Report Sls. No. 53789

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/32.)

st No. 3

**ADVANCED
SURVEY PARTLY HELD.**

on due 12.32 When proposed to be completed on vessels return in about
4 months time.
tion of Survey held, &c.,

To complete the survey:— See Report.

21/9/33

30.8.33

It should be pointed out to the Surveyors that in addition to the items stated as remaining to complete the survey it would appear that the vessel requires to be examined in drydock & it is concluded it was not considered necessary to drill the shell plating but the Surveyors should state if this is so.

I am, Dear Sirs,