



Lloyd's Register of Shipping,

Royal Bank Buildings,
28, Constitution Street,

Leith, 4th January, 1940.
Edinburgh, 6.

RETAIN

Reference

S.

Dear Sir,

With reference to your classing letter of the 29th ultimo in the case of the s.s. "CROWN ARUN" we have to confirm that we were satisfied on examination that the deck beams and their supports throughout the vessel were in good condition, and were heavy enough for their requirements.

The electrical steering gear was seen in operation in dock, and from a report received from the Managers it would appear to have given every satisfaction on the first voyage.

With reference to the entry on our Electrical Report No. 19982 that Earth Lamps were fitted, this of course was entered in error and we regret same. The fuses should not have been reported by us as being of a type approved by the Society, but they appeared to be satisfactory. They are of German pattern, and we are pleased to learn that they have been accepted in this instance.

We are, Dear Sir,
Yours faithfully,
THE SURVEYORS.
Per.

The Secretary,
WOKINGHAM.

2019
John Houston
Lloyd's Register
Foundation

W378-0161

H

RS

15-JAN 1940

78

14

NOTED
1.0.0



© 2019

Lloyd's Register
Foundation