

1

SS TEL N° 3-10 37
26 NOV 1942

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "EMPIRE SAILOR" REPORT Liv. No.118650

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey GEN. EXAM. FOR POST. OF 2ND S.S. ~~When due~~ No. 1, DUE 10.41.

"EXAMINED 11-42", 12 MONTHS

Subject to No.11 D.B. tanks being tested
on discharge of present cargo, tank not to be
used as such meantime and to (a bower anchor being
supplied).

copy
26.11.42

"Examined 11.42"



© 2019

Lloyd's Register
Foundation

1038-0081

Transverses

efficient ?

Ironbands

Breasthooks & Stimson

Cables (State if new)

length

where examd. Good.

Have Watertight Doors been examined and found

HLLo
TSC
DIL
), as
rified
ot
Lin
Ks
me
ed
re
n
(
f
ilt.)
nth
seer
es re