

4 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Empire Sailor

Rpt.

By John.  
Rev.

No.

221.  
118650

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

C.A. advanced.

It is submitted that  
this vessel is eligible to  
remain as **CLASSED**

Suggest to fix & test pump valves  
check being removed as first opportunity

Examined 11.42 for 12 hrs

No further should be changed  
for 12 hrs at the time

Thur  
23. 11. 42

Lloyd's Register  
Foundation

W38-0088

the after lub. oil pump examined.