

Dear Sirs,

With reference to your Freeboard report No. 6054

BOARD REPORT on the S. S. "Wendland"

This submitted the Surveyor he informed that before freeboard certificates are issued he should forward particulars regarding moulded depth, length of poop, position of side scuttles, and supports in No. 6 hatchway on poop, all as requested in Secretary's letter dated 28.10.21. The height of the side scuttles above top of keel should be carefully checked.

H.R.

28.12.21



© 2021

Lloyd's Register
Foundation

W380-0195

Secretary.