

FREEBOARD REPORT on the

S. S. "Wendland"

It is submitted the Surveyor be informed ~~that~~ the freeboards have been assigned on the assumption that the moulded depth is $41-3\frac{7}{8}$ as shown on the plan of midship section and not $38-2$ as given on his report; the length of the poop is $65-2$ and not $82-3$ which is presumed to include the overhang abaft the sternpost; and the distance between the sill of the lowest side scuttle and the top of the keel is $31-5$ but he should confirm these items.

The fee to be charged for freeboard assignment should be £15. The Surveyor should also forward particulars of the supports in No 6 Hatchway on Poop.

W.D. S.W.B.
28-10-21
Lloyd's Register
Foundation

W380-0197

vessel to any other authority appointed in accordance with section 2 of the Merchant Shipping Act, 1890 (except in respect of a similar certificate, dated