

... position [or alteration of the position] of the centre
disc on this vessel to this or any other authority appointed in accordance

7
- 1/2

FREEBOARD REPORT on the S.S. Diplomat

It is concluded the storm boards at
after end of bridge are fitted in riveted
channels but the Surveyors should
confirm this.

GRM
17.2.21



© 2021

Lloyd's Register
Foundation

W382 - 0044

Poop	54.29	54.04	7.25
Total		<u>288.76</u>	
Length of Ship			

Winter Freeboard from deck line

8.33/4