

S.S. "DUQUESA"

RETAIN

It is submitted that the Owners' letter dated
May 15th should be returned to the West Hartlepool Surveyors,
and they should be asked to state if this Vessel was
examined in Dry Dock, and the last date of Survey.

in the Register.

F.R.N.
11. 6. 18.

Lr Hpl 11/6/18
Copy owners letter



© 2020

Lloyd's Register
Foundation

W383-0093

FURNESS-HOULDER ARGENTINE LINES LTD.,