

W383-0161

Surveyors

Received from Chief Surveyors

NAME STEEL S.S. "DIONYSIOS STATHATOS"
EX. "WAR CADET"

Report LIV.

No. 79596

For the CHIEF SHIP SURVEYOR

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

by

When due

* 100 A.1. (steel)


1 Dk. (steel) "Webframes"

Cell DB 343' 1152t. Dta 28' 1215t. FPT 113t. APT 166t.

FK. 7BH. pt. com. Lloyds A.Y.C.P. P49', B113', F 40'.

M. A.S. 25.9.19

It is concluded, the 2nd Deck beams and plating in way of Machinery have been fitted in accordance with the approved plans, that the Collision Bulkhead is as approved & that semi box beams have been fitted as per approved plans, a horizontal web has been fitted as required on other Bulkheads, that the 1st of double bottom forward is as in ^{2nd} vessel, also that the thickness & riveting of strake & strake below clear of bridge is as approved, but the Surveyors should be asked to state if this is so, & in future cases to insert particulars of shear strake or of bridge in the space provided in the report.



© 2020
Lloyd's Register
Foundation