

11.39.

ived by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SEL'S NAME "EISYO MARU" Rpt. Kob No. 11481

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

The Kobe Surveyors report the vessel placed in dry dock, the bottom coated, 2 shell plates repaired, renewals to a deck plate and 2 inner bottom plates and to a number of hatch covers.

It is submitted the vessel appears worthy to remain as classed with record of survey 4.40.

100A1
4.40 Kob

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.



© 2016 40

Lloyd's Register
Foundation

W 385 000 2