

5 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

L'S NAME "ELI KNUDSEN"

Rpt. Bgn.

No. 2867

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

of Survey

ICE DAMAGE & -WEAR-AND-TEAR.

Both screw shafts examined and both propellers found damaged.

2 spare propellers now fitted.

It is submitted the vessel is eligible to remain as classed with record of Survey Both ~~3~~<sup>3</sup>.40 as recommended.

RETAIN

R

© 2019

Lloyd's Register Foundation

W385 - 0035

13.3.40