

State latest date of internal examination of each boiler? *Yes.* To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Main Boiler?

4m, 11, 38.

2 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "EMPIRE CONVEYOR"

Rpt. Nwc.

No. 98346

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS~~ FOR S.S.-No.

This Survey, due 11.39 ~~now~~ partly held 1.40 now

completed, and the following repairs carried out (due to wear and tear):-

A few screw stays renewed, machinery also examined and various minor repairs effected.

It is submitted the vessel is eligible to remain as classed, with notation of BS 1.40 as recommended.

© 2019

Lloyd's Register Foundation

1.4.40

The opportunity was taken at this time for a general overhaul of the machinery. Continued on Page 2