

# Lloyd's Register of Shipping

ROOM 208 LAKE OF THE WOODS BLDG.

MONTREAL, June 21st, 1921.

The Secretary,  
London, England.

Dear Sir:-

LOYD REGISTER  
DON.  
REC 5<sup>th</sup> JUL 1921  
ANS- x

S.

In reply to your letter of the 31st, of May, regarding the Montreal report 1891 regarding the "CANADIAN COMMANDER" and have to state that the rivetting on the bridge side plating is as required by the rules. The fees for the survey of the electric lighting installation have been charged to the builders and paid by them. It was an error on my part in omitting to mark these fees on the report.


RETAIN

Montreal report 1893 "LORD STRATHCONA"  
The date of the first visit for the hull was April 28th, and the last visit May 10th, number of visits six.

The date of the first visit for machinery was May 2nd, last visit May 10th, and the number of visits four.

Yours very truly,

*M. J. Alderson*



© 2019  
Lloyd's Register  
Foundation

W387-0315

W387-0316

2

*Field*

F.

189

mitte

Lin

but

31

4

26-5-

the

Referred to the Chief Ship Surveyor,  
and the Surveyor General.

*[Handwritten signature]*  
-5 JUL 1881

Also for Mr. S. A. Hill to note.  
Referred to Mr. ~~Maxie~~

*[Handwritten signature]*  
57-20

Bell  
6/7/21



© 2019

Lloyd's Register  
Foundation

Less Crew Space  
Less above Crown of  
Engine Room

red by Chief

SEL'S N

The remark

Transv

Framing

Longit

*[Handwritten initials]*

*[Handwritten text]*

*[Handwritten text]*

Rules a  
be clari

*[Handwritten text]*