

ived by Chief Ship Surveyor.

SEEL'S NAME Stal S. S. "CANADIAN TRAVELLER" Rpt. Va No. 841

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Longitudinal No. 3322

Bully Deck Sheerstrake as approved

✠ 100. A-1. (Stiel)

2 Dks (Stiel)

Cell IB 329' 1026t, FPT 149t, APT 131t

FK, 6BH, Hlyps Ave, P49, B113, F38
 Dat of breed 3, 21.

It is concluded the Rowsers & Woups are as in the Sister vessel
"Canadian Winner" and not as stated but the Surveyors should be requested
to state if this is so and whether the record of "Cens" or "pt Cens" should
be made in this case.

Lloyd's Register
Foundation

W 389-0136

Plate, Toe Bulb, or Channel.....	}
Angles on upper edge	

* If Iron or Steel Deck, state if whole or part, and if Wood Deck is laid thereon.