

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Stl. S.S. "DESDEMONA"

Rpt. Lth.

No. 15923

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

Before this case receives consideration, the Surveyors should be requested to state whether all the requirements of Section 48 of the Rules have been carried out, if the workmanship was found satisfactory; and whether web frames are fitted in the Engine and Boiler Space, as in the sister vessel, if so, particulars of the same should be given, together with particulars of pumps.

It would also appear that 45 fathoms of chain cable are required to bring the cable up to the length required by the Rules, and not thirty fathoms, as stated by the Surveyors.



© 2020

5.4.21.

Lloyd's Register  
Foundation

W39-0147