

PORT on the

S.S. "Peradovic"

His submitted the Owners be reminded that
freboards were assigned to this vessel subject
to permanent closing appliances being fitted
to the openings in the bridge front and as
it has been reported that the Society's freboards
have been marked on the vessel's sides they
should state when and at what port the
necessary alterations will be made.

M.R.S.



2.5.28 © 2020

Lloyd's Register
Foundation

W394-0042