

REPORT of SURVEY for REPAIRS, &c.

When handed in at Local Office 6. 4. 1927 Port of Rassy

Survey held at Rassy Date, First Survey 23. 3. 27 Last Survey 4. 4. 1927
on the Wood, Iron or Steel Sc. L. Peradovic, ex Kiel.

INNAGE:- Built at Vegesack By whom, D. Med. Dulean When 1907
5341 Owners Jugoslovensko Amerikanska owners' Address
DK 5020 Slovian (if not already recorded in Appendix to Register Book).
3418 Managers Port belonging to Split.

Used Afloat or in Dry Dock Afloat Name of Dock Rassy Dock Destined Voyage
Cell DBor DBa feet; uE&B feet; f feet
capacity tons. FPT tons; APT tons; MT feet tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

E. All alterations in the existing records should be underlined.
The Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Report, No. Port

Local Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the movement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

Where the Surveyor has not made a special damage report he is required to state whether he has declined his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR part 1st. No 3. for ultimate classification
see Liverpool Report No. 91674.

Attended by request to examine No 2 double bottom tank internally & found it unprepared & to have mud & water all over the bottom. No examination could be made. also asked to see Nos. 1 & 6 ballast tanks under pressure with about 1 1/2 of the tank top ceiling lifted & timber boards up. the tanks were tight, the tank tops & bilges require sealing. nothing further was done as the vessel proceeded to load.

All the requirements remain to be carried out as stated in Liverpool Report.

STATE OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Fairred or Repaired								
When tested Fairred or Repaired in place								

GENERAL CONDITION OF THE	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt)
Bulkheads	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Fastenings	Ceiling	Scuppers	Boats
Plating	Cement or Asphalt (state which)	Cargo Hatchways	Masts, Yards, &c.
Locks	Rudder	Hatches	Condition, how ascertained
Frames	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
Frames	Windlass	Caulking ditto	Sails
Frames	Have Pumps now been examined and found efficient?	Treenails ditto	Equipment letter
Frames	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Frames	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	length size
Frames		Ditto ditto at other places ditto	(on board) size
Frames		Stringers, Clamps & Shelves ditto	Rule length size
Frames		Salting ditto	Hawser & Warps
Frames		(State if examined)	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,2,4," or "to remain as classed and to have record of survey, 1,2,4, and the notations of ss No. 1-24 and ptND15, &c."

Submitted for information of the Committee.

Fee (per Section 20) £ : : Fees applied for, 19 :
Damage or Repair Fee (if any) £ : : Received by me, 19 :
Expenses (if chargeable) £ : :
Surveyor's Fee (if any) £ : :
Surveyor to Lloyd's Register of Shipping.

Committee's Minute TUES. 12 APR 1927 TUES. 20 SEP 1927 TUES. 22 MAY 1928 FRI. 23 JAN 1931

Character Assigned No action FRI. 18 MAY 1928 FRI. 12 OCT 1928 FRI. 21 JUN 1929

FRI. 28 OCT 1927 FRI. 24 AUG 1928 FRI. 28 JUN 1929

TUES. 15 MAY 1928 TUES. 12 NOV 1929

Lloyd's Register Foundation

Is Certificate required? If so, to be sent to

W 394-0089

It is submitted that as the survey for classification is incomplete no action is necessary on this report.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form.

ANCHORS.

ANCHORS.													
Number of Certificate.	Anchors.*	WEIGHT OF STOCK.		WEIGHT OF STOCK.		TEST. PER CERTIFICATE.			WEIGHT REQUIRED BY RULE.		Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	lbs.	Cwts.	lbs.	Tons.	Cwts.	lbs.	Cwts.	lbs.			
	1st Bower ...												
	2nd "												
	3rd "												
	Collective Weight.												
	Stream												
	Kedge.....												
* When a bower is used, the weight of the bower must be entered in the column headed "Stream."													
If Patent state name of Patentee.													

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower

CHAIN CABLES.

[illegible]

Iron Stream Chain
or Steel Wire...

8.4.27

