

S.S. "GALAXIAS"  
-----

Mr. Dutton, the owners' representative, called to discuss the question of the fitting of the doubling to the stringer plate in this vessel referred to in the Secretary's letter.

Mr. Dutton explained that it would be very difficult to fit this doubling in way of the side house amidships. It was arranged that the doubling would be fitted as required beyond the side house and that, in way of this house, the strake adjacent to the house would be doubled with a plate having the same sectional area, and this doubling would overlap the stringer doubling about 2 frame spaces at each end.

It is submitted the owners be informed accordingly.

Mr. Dutton stated he would call for this letter tomorrow morning.

W.T.

30th October, 1939.

In Owners 30/10/39



© 2020

Lloyd's Register  
Foundation

W398-0202