

2<sup>o</sup> JULY 1940

Inspected by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME "HEDRUN" Rpt. Mch No. 10,042

**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

The class is subject to temporary repairs to shell plates (s.s.a.) No. 5 in 1st below sheer and No. 4 in 2nd below sheer being examined at Manchester where bound.

The Manchester Surveyors now report the vessel afloat, temporary repairs, as above, examined and the recommendation made that permanent repairs be effected at the Owners' convenience.

It is submitted this vessel is worthy to remain as classed without record of survey, subject as recommended.

As Now, Subject, etc.


Wals  
27.6.40



© 2019

Lloyd's Register  
Foundation  
W 400 - 0114

The information in this report is based on the information provided by the ship's crew and is not intended to be used as evidence in any legal proceedings. The information in this report is based on the information provided by the ship's crew and is not intended to be used as evidence in any legal proceedings.



© 2019

Lloyd's Register  
Foundation