


S.S. "Hjalmar Blomberg."

It is submitted the Malmo Surveyors be requested to state whether the Screw Shaft of this vessel is fitted with a continuous liner. as this has not been mentioned on the report.



© 2019

B.C.M.

10/11/20

Lloyd's Register
Foundation

W 400-0 141