

26F-2E0

1.38.

Inspected by Chief Engineer Surveyor.....


Received from Chief Engineer Surveyor.....

VESSEL'S NAME "ISLAND QUEEN" Rpt. Lon. No. 108349

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES-AND BOILERS FOR S.S.—No.



This Survey, due 5.40 ^{now} partly held 1.40 now completed, ~~and the following repairs carried out (due to~~):-

It is submitted the vessel is eligible to remain as classed, with notation of BS 1.40 as recommended.



© 2019

Lloyd's Register Foundation

W401-0043

23.2.40

Man

Engine parts, when referred to by numbers, should be counted from forward.

Is electric light and/or power fitted

Will the Surveyor examine the generators, motors, switchgear, cables and fuses?