

Inland Queen

Mr. Davis, Superintendent, states that dynamo engine  
governor is not yet satisfactory & that a new  
engine is to be fitted. but that this will not  
take place for a few months yet.

Geo. L. King 9/6/34

L  
Lloyd's Register  
Foundation  
W401-0050

Clerk to the  
Classification Committee.