

m.11.38.

4 E

Received by Chief Engineer Surveyor .....

Received from Chief Engineer Surveyor .....

VESSEL'S NAME "GOATHLAND". Rpt. L.A. No. 7195.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

See endorsement dated 27.5.40.

*20.10.1940  
5.40*

A further report of a survey held by Lloyd's Agents at Freetown, Sierra Leone, has been received.

The Surveyor states that one of the thrust shoes is cracked and he recommends it be renewed and the other thrust shoes remetalled.

He also recommends repairs to the circulating pump engine and that the other parts of the main engine be opened up for examination.

The vessel was apparently still under <sup>repair</sup> survey at that port.

It is submitted action be deferred and a report awaited.

W403-0002

© 2020  
27.8.40.Lloyd's Register  
Foundation

*Chas. Campbell*  
ENGINEER