

Hull R.R. No 31941

COPY.

# Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

D. B. B.

Enclosure.

24th April, 1920.

Dear Sirs,

I return herewith for completion Hull Report No. 31752 on a new boiler for the Tug "GUARDSMAN", which it is observed is to be fitted on board in a few months' time.

I shall therefore be glad if you will give the case the necessary attention in due course, and you will be so good as to return the enclosed Report when the boiler has been fitted on board.

I am, Dear Sirs,

Yours faithfully,


Secretary.

Blr approved 14th 22/9/19  
original press 13076

The Surveyors,

HULL.

Screw shaft Rule 7 1/2 inches  
fitters 7 1/4



© 2020

Lloyd's Register  
Foundation

W403-0128

separately ✓ Diameter ✓ Length ✓ Thickness of shell plates ✓ Material ✓ Description of longitudinal  
holes ✓ Pitch of rivets ✓ Working pressure of shell by rules ✓ Diameter of flue ✓ Material of flue plates