

8 MAY 1940

Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

NAME "GIANNOULIS GOUNARIS".

Rpt. Cff. No. 53407.

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

A considerable part of the 3rd Special Survey No.3, due 10,38 has been held.

Permanent repairs are required to damaged stem plating and the chain pipes require to be renewed.

In April last after a General Examination in dry dock an extension of time until October next was agreed to and a record Examined 4,40(in red) was inserted in the Register Book.


The Cardiff Surveyors now report the chain pipes referred to above, renewed.

It is submitted action be deferred.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

Delete from S.R.L:- 'Chain pipes'

7.5.40



W 403-0180

65. efficient?	Transoms Pointers, & Crutches ditto.....	Cables (State if no
Have Watertight Doors now been examined and found	Timbers of Frame at openings ditto.....	" length.....
efficient?	Ditto Ditto at other places ditto.....	(on board
	Stringers, Clamps & Shells ditto.....	" Rule length.....
		Hawser & Wires