

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "HYLTON" Rpt. Vcr No. 5527

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The VANCOUVER Surveyors report this vessel placed in dry dock, the bottom coated, and on account of damage through encountering heavy weather a number of shell and internal rivets renewed, repairs to deep tank and minor repairs effected.

The requirements of the 1st S.S. No. 1, due 1.41, have been partly complied with.

It is submitted the vessel appears worthy to remain as classed with record of survey 1.41.

100A1
With fbd
1.41 Vcr
Carrying vegetable
oil in deep tank.

Amend in R.B. Equipment letter at to at 2"

The Surveyors should be informed it is concluded that in addition to the items remaining to complete the Survey mentioned in the Report the deep tank requires to be tested and the machinery space to be examined, but they should be requested to state if this is so.

Handwritten signature and date 31.3.41

© 2020 Lloyd's Register Foundation
W 404 - 000 4
S.S. Part held