

46185 on the Steel No. 1070
TONNAGE:— Built at Sunderland By whom H. Pickergill & Sons Ltd.
GROSS 517

REPLACEMENT COPY. WRECK SECTION. No. 499- 12 SEP 1941

Lloyd's Register of Shipping.



Port Halifax, Nova Scotia,
March 15th, 1941.

This is to Certify that I have

Surveyed the M/V "HYLTON", 5197 gross tons register of Newcastle,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have **Recommended** that she be continued as classed subject to indented sheer strake and bulwark plating, boat deck stanchions, engineers accommodation bulkhead and deck piping in way (p.s.) amidships being repaired at owners convenience, being fit to carry dry and perishable cargoes.

W404-0016

- en. Renew gripping spar.
- (Signed at carried Renew.
- damaged. Repair damaged boat and cho

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any liability or responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors or other publication of the Society, or for any error of judgment, default or omission of any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.)

© 2020 Lloyd's Register Foundation
gible, in
work plat
ing in way