

D REPORT on the

S.S. "Humber Iron"

It is submitted the Surveyor be requested to state the depth of the web plates fitted in the Ratchways, the height to which the storm boards are fitted in the openings in the tween deck bulkheads adjacent to the tonnage opening and whether the channels are riveted to the bulkhead, this information having been omitted from his report. He should also report whether storm valves are fitted to the scuppers led overboard from the tween decks. It is noted the length on the waterline is given as 424.9 feet instead of 422 ft. as given when the plans were approved, and the Surveyor should confirm this.

S.W.B.

19-3-25

Lloyd's Register
Foundation

W404-0126