

2m.10.39.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

"HALLAND".

Report

Gls.

No.

62427.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

GENERAL EXAMINATION.

Nature of Survey

When due

Noted.

7.6.40.

Shell plating starboard side in after hold abreast No.3 hatch and abreast mainmast is indented.

Insert in S.R.L.:- Exd L.R./^{5.40}-for 6 mos.

Note: This is one of the Danish vessels classed with the Germanischer Lloyd or Norske Veritas and taken over by the Ministry of Shipping concerning which the Committee recently agreed that provided they were found or placed in satisfactory condition for a period of six months, after general examination as set forth in Circular 1764, a record of Examined L.R. (with date) could be inserted in the Register Book.

Lloyd's Register
Foundation

W405-0051

Have the Tanks been tested?

Doubling plates under sounding pipes

(State if necessary)

to Class Recommendation, &c.:-