

S.S. "HARBLEDOWN"

It is submitted the Glasgow Secretary be informed that in cases such as this where the pumping arrangements outside the machinery spaces are fitted at the port where the vessel is built and the vessel is subsequently brought to Glasgow to receive her machinery, that the Surveyors who supervise the fitting of the hold suction &c. should note the fact in their Machinery report and give the required particulars of the connections.

It was concluded from the Glasgow Secretary's letter dated 13th July 1932 regarding the steamers "HARMATRIS" & "HARMANTEH" that this had been pointed out to the Greenock Surveyors, but the Surveyors at that port make no mention of the matter in their report No.19543 on the subsequent case of the steamer "HARBLEDOWN".

*Le H. 18/5/33*

*SA 16/5/33*  
*AL*



© 2019

Lloyd's Register  
Foundation

W405-0208