

25th February, 1939.

B. 2m, 10, 38.

FREEBOARD REPORT on the

'HARLESDEN'

It is submitted the Cardiff Surveyors be requested to state the condition of the coamings and closing appliances of the ventilators in the poop deck leading to the poop space the openings in the poop bulkhead being provided with class 1 closing appliances. They should also state the condition of the machinery casing and the doors thereon inside the bridge space the openings in the bridge after bulkhead being fitted with class 2 closing appliances.

The Surveyors should state if the gangway from the bridge to the poop has been removed and lifelines fitted in lieu thereof because the Report C11 gives details of a gangway while the Report C12 gives only the condition of lifelines.

It is assumed that the Bridge forward bulkhead has no closing appliances and the Surveyors are in error when they report closing appliances on the bridge front in good condition.

A.L. 18/3/39

51.8
W 405-0267

With regard to the "HARLESDEN", we hope that