

COPY.

Copy of a letter received from the Glasgow Office dated 9th
February, Received 10th February.

GLASGOW,

9th February, 1920.

ENCLOSURES.

A. 51
51
2.
Sir,

RETAIN

With reference to your letter of the 5th instant respecting
Glasgow First Entry Report No. 39560 on the Steamer "HARMONIDES",
I beg to acquaint you that the Surveyor states that the widths of
the bottom plating are less than 84 inches, and that the riveting
in the edges of the sheerstrake and bridgeside plating and of the
strake below the sheerstrake clear of the bridge is as required.

With regard to the equipment of this vessel, it is
regretted that owing to a misunderstanding the wrong particulars
of equipment were reported in the case of the Steamer "HARMODIUS",
Glasgow Report No. 39259, and I beg to enclose herewith the correct
particulars for that vessel, which I shall be glad if you be so
good as to substitute for those already sent.

I may explain that the report on this case was written
by Mr. Moir in the absence of Mr. Meek, and that the mistake is
largely due to the fact that the name of this vessel was changed no
less than three times during the course of her construction.

Lloyd's Register
Foundation
I am, Sir,

W406-0176

