

1

"Harport"

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "LAKE FAIRPORT" Report Detroit No. 231**For the CHIEF SHIP SURVEYOR** ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey

When due

The Downton Pump has been dispersed with for the present.

X 100 A-1. (steel)

1 Dk (steel). 2 trs beams.

Cell DB 204' 472 t. Dta 12' 39 t. FPT 72 t. APT 107 t.

FK. 4BH. pk. cmz. A9C.F. P 25', B 64', F 23'.

W406-0224

© 2019

Lloyd's Register
Foundation