

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"HERPORT".

Rpt. Hul.

No. 48699.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Survey for reclassification

Engines and boilers examined throughout.


Wear and tear:- Screw shaft, some boiler tubes and boiler mounting fastenings renewed.

A condenser repaired and some minor repairs effected.

Dynamo renewed.

It is submitted the vessel is eligible for the record *LMC 3,38, S(N) 3,38. (C.L).

Register Book particulars as before.


23.3.38.



© 2019

Lloyd's Register
Foundation

W406-0234