

Lloyd's Register of Shipping.


REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship *"HERPORT"* Official Number *166344* Port of Registry *London*
Place of Survey *Istanbul* Dates of Survey *21/3/939* Date of last Load Line Survey *Certificate issued 1st December 1938*

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
Exposed on freeboard deck.			
Timberings, their stays and stiffeners...	In good condition ✓		
Planks ...	In good condition ✓		
Fore and afters ...	✓		
Covers ...	In good condition ✓		
Tarpaulins ... (State number per hatchway)	In good condition ✓ 2 per hatchway ✓		
Cleats and battens ...	Good ✓		
Fittings and their fittings ...	Good ✓		
Wedges ... (Is supply, including spares, adequate ?)	good + adequate ✓		
Exposed on superstructure decks, including raised quarter decks.			
Timberings, their stays and stiffeners ...	In good condition ✓		
Planks ...	✓		
Fore and afters ...	✓		
Covers ...	In good condition ✓		
Tarpaulins ... (State number per hatchway)	In good condition ✓ 2 per hatchway ✓		
Cleats and battens ...	Good ✓		
Fittings and their fittings ...	good ✓		
Wedges ... (Is supply, including spares, adequate ?)	good + adequate ✓		
Within superstructures not intact or not protected by Class I closing appliances.			
Timberings ...	✓		
Planks ...	✓		
Fore and afters ...	✓		
Covers ...	✓		
Tarpaulins ... (State number per hatchway)	✓		
Cleats and Battens ...	✓		
Wedges ... (Is supply, including spares, adequate ?)	✓		

*Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).
No. 1137. T. (MADE IN ENGLAND.)





© 2019

Lloyd's Register
Foundation

W406-0274(1/2)

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	In good condition ✓ good		
Closing arrangements			
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	In good condition ✓ good		
Closing arrangements			
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	good ✓		
7. Within partially enclosed superstructures.			
Closing arrangements	good ✓		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddle openings, their covers and fastenings	In good condition ✓ In good condition		
Skylights, their fastenings, covers and lashings			
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	In good condition	none	
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	In good condition ✓		
11. Within partially enclosed superstructures.			
Doors and fastenings	In good condition ✓		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	✓		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	In good condition ✓		


Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS.			
Forecastle	Hinged Steel door, good	✓	
Bridge, fore end...	Hinged steel doors, good		
Bridge, after end	Hinged Steel doors, good		
Poop	Hinged Steel door, good		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	✓	RETAIN	
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	In good condition ✓		
17. SIDE SCUTTLES AND DEADLIGHTS			
	In good condition ✓		
18. GUARD RAILS			
	In good condition ✓		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	✓		
20. LIFELINES (fittings and material)			
	Fittings & steel wire ropes in good condition ✓	RETAIN	
21. FREEING PORTS			
Shutters	✓		
Protection bars	In good condition ✓		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	✓		
23. ITEMS NOT INCLUDED IN THE FOREGOING			
	✓		
24. LOAD LINE MARKS			
	Checked & found to be in accordance with Load Line Certificate		



© 2019 Lloyd's Register

RETAIN

RETAIN



© 2019

Lloyd's Register
Wholesale and Retail

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11.

Two manholes have been opened on Bridge Deck, one on Port
+ one on Starboard side, for the purpose of trimming bunker
in Bridge Space. These manholes are closed by means of steel
covering plates bolted to the deck.

For Comd Rm Jh.b.

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular 16
and the requisite details of the survey have been entered herein.

Index Nos. of items examined. †	Signature of Surveyor.	Place.	Date.
all	Jh. Lamplund	Istanbul	21/3/1939

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

I have surveyed this ship for the purpose of seeing whether this Certificate should remain in force and the Survey has been completed to my satisfaction.

Signature of Surveyor

Jh. Lamplund

Place

Istanbul

Date

21/3/1939


Signature

Jh. Lamplund

Date


21/3/1939

† Insert "all" in case of a complete survey.



Fee
Lloyd's Agent
10.00
Number of Visits
One

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.



© 2019

Lloyd's Register
Foundation