

Less above Crown of
Engine Room ...
Manila ...

31.02
243.84

2nd Number ...

7499.

Managers v H. H. S. Sme
(Where necessary to be entered in Reg. Book).

(1m,2,5.)

1.

Sent to Chief Surveyors 5. 5. 05

Kyle Ruth

Received from Chief Surveyors

VESSEL'S NAME *See S.S. Senza*

Report *See* No. 22740

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

When due

+ 100 A1 ("Steel")

1 DR (See) Well back

N.B. = FPT 48 L APT 2 L

BK 7" 3 BH Cam. *Plough A+CP* 986' 810' F 23' *McKay Aft.*

C. A. J. 5/5/05

RETAIN



© 2019

Lloyd's Register
Foundation

W407-0032

WEB FRAMES, In Fore Body, No. and Spacing

Tie Plates
Deck, Material and thickness
* If Iron or Steel Deck, state if whole or part, and if wood