

2m.9.47.

W409-0133

FREEBOARD REPORT on the BRITON.

Submitted that the Barry Surveyors be requested to confirm that the hatches inside the bridge and forecabin
are in good condition.
It is submitted that any ^{copy of the} additional L/B cert be forwarded to the owners.

G.H.W.

3- SEP 1948



© 2019

Lloyd's Register
Foundation