

S.R.L.:— Indented. plates F2,3 &, and E1, G4, H4,5 (s.s.), E3,4 F5 (p.s.)

Im,7,41.

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME GAZCON

REPORT N.Yk. No. 42554

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DOCKING

When due

Subject to indented shell plates F.2  
and 3 (s.s.) and frame and stringer in way, also  
E.3 & 4, F.5 (p.s.) E.1, G.4, H.4 & 5 (s.s.) being  
dealt with at the Owners' convenience.



22.7.42

© 2019

Lloyd's Register  
Foundation

W41-0003

This vessel is in safe condition & eligible in my opinion to be continued