

If Stockless, state Mechanical Tests.

THE SURVEYORS ARE REQUESTED NOT TO

Screw shaft now been drawn and examined? *yes* Is it fitted with continuous liner? *no* or two liners? *no* or is it with

SS. Leo en Spes.


This vessel was built in 1908 by the Stettiner
Göderwerke & has now been surveyed
for Classification with this Society.

The machinery & boilers have been opened
up & examined & repaired as necessary.
The screw shaft has been drawn & a
satisfactory report received.

It is submitted that
this vessel is eligible for
THE RECORD. LMC. 2-21.

S. 2-21.

Recd.



© 2019

Lloyd's Register
Foundation
W410-0188