

Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

The class is subject to the casing of the port circulating being examined at next G.E.

2 E

Engineer Surveyor

Received from Chief Ship Surveyor

114 JUL 1948

NAME

PORT SYDNEY

REPORT

Cff.

N56153

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also setting out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points mentioned in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

COMPLETION OF SPECIAL SURVEY OF ~~ENGINES-AND-BOILERS~~ 90R-S-S-Ne-

This Survey, due 10.47

~~now~~ partly held

11.47

now

Completed, and the following repairs carried out (due to -----):

1.:- Port circulating pump examined under working conditions and found efficient.

Surveyor recommends this pump be again examined by 8.48.

It is submitted the vessel is eligible to remain as classed, with

condition of BS 11.47 subject as recommended.

12.7.48

© 2019

Lloyd's Register
Foundation

W 412-0221