

Presented to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

"HIGHWAVE"

Report

LW

No.

112735

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor

Condition

When due

Subject to the rudder post of the sternframe  
where recessed in way of propeller + surface  
fractures on port + starboard sides of the solepiece  
repaired by E.W. 12.37 + 6.39 + doubling plates  
being specially examined at next dry  
docking.

The Certificate of Classification to  
be endorsed "Cargo battens not  
fitted" and the same notation to be  
printed in the Register Book.



© 2019

 Lloyd's Register  
Foundation

 W/L  
29.6.39

WWS 10098